

Frankstown Township.

The road leading from Hollidaysburg to West Loop, which was in excellent shape last year, having been newly resurfaced with stone, has apparently received no attention during the past season. On one section of this road in particular, the bank has slipped, filled up the ditches completely and scattering mud over half the width of the stone portion of the road. We feel that the supervisors should be most severely censured for allowing conditions like this to exist, especially on a road that was as well constructed as this one. The road leading from the West Loop road to Mc-

Cune's Mill is in fairly good shape, about a thousand feet of it having been resurfaced with stone, but this stone was placed along one side of the road rather than in the middle of the right of way. The road from Frankstown to East Loop was in very good condition, there being about three-fourths of a mile of new resurfacing with stone. The road leading from East Loop to Menser's Mill was in very bad shape, two new breakers being found. The road leading from Menser's mill to Dutch bottom apparently had little work done on it, but the Dutch bottom road was found in fair condition; well crowned and ditched. There are still three breakers on this road. The Turkey valley road, leading from Frankstown into Turkey valley, we found greatly improved, being nicely ditched on both sides and well crowned, and wherever improvements had been made, the breakers were eliminated. There are, however, still seventeen breakers on this section. The road from Turkey valley to Scotch valley was in about the same condition as last year, and the road leading from Turkey valley to Canoe Creek last year, and the road leading from Turkey valley to Canoe Creek was in fairly good shape for a road of this character. The Scotch valley road was somewhat improved, though the breakers are rather numerous, twenty-eight having been eliminated and the road resurfaced with stone, and ditches nicely opened. The Brush mountain road in this township was found in fair condition. The road leading from the old turnpike to Frankstown was in good shape, the ditches having been opened up and the greater part of the road being well crowned. There are, however, twelve breakers on this road that might very well be dispensed with. The Frankstown road leading to the Brush mountain road was in rather fair shape, but three breakers being noticed. This township has also erected fingerboards at the principal road intersections.